

Abstract

The Thesis is dealing with structural damage of the buildings of Osek Monastery from the point of view of engineering geology. First the previous engineering geology and geotechnical investigations are reviewed, then a catalogue of found damage is presented. The influence of ground water, and especially the malfunction of the historic water system of the monastery is considered to contribute to the structural damage. The nearby mining activity however was found to have no effect on the buildings.